

⑥ Mounting the module

- Position the first module flush with the end of the rail, then observe the indentation distance **d** (c.f. Autokalkulator schematic diagram and information issued by the manufacturer)
- Fasten module with two end clamps - in our example: click in the Rapid end clamps and tighten the 6-Lobe screws (T40).
- Connect the module cables as required.
- Position further modules and secure each between the modules with two middle clamps.
- Secure the last module of the row with two end clamps.

